



Figure 43 Propeller Assy.

Index

No.	Part No.	Description	Cond.
	41D5926-SS135-6	Propeller assy-McCauley	O/H/C
1	SS-135-6	Blade-propeller	
2	41D5926	Hub assy-propeller	O/H/C
3	40D-1723	Clamp-41D5926 hub	O/H/C
4	AN5000-9	Bolt-41D5926 hub clamp	N-S
5	AN5001-9	Nut-AN5000-9 bolt	N-S
	Attach hdw.	AN380-4-4	F/N
6	AN5008-20	Cone-propeller hub-rear (bronze)	N-S

PROPELLER ASSEMBLIES, R-670, PG-17, N2S-4, PT-13, N2S-5 continued

Figure 43

Index

No.	Part No.	Description	Cond.
7	AN5007-20	Cone-propeller hub-front (steel)	N-S
8	AN5009-20	Ring-propeller hub-snap	N-S
9	AN5011-20	Nut-propeller hub-retaining	N-S
10	AN394-17	Clevis pin	F/N
	Attach hdw.	1 ea. AN960-416, 1 ea. AN380C2-2	F/N
	98JA Series	Propeller assy-wood	F/N
*11	98JA Series	Propeller less hub assy	F/N
12	41G2325-9	Hub assy-contains index #12, #13, #14 & #15	N-S
12	41G2326	Hub-back half	N-S
13	41D-2327	Clamp-front half hub	N-S
14	41B-2329-12	Bolt-hub attach, 8 required	F/N
15	33A1976	Nut-hub bolt, 8 required	F/N
	Attach hdw.	AN380-4-4	F/N
6	AN5008-20	Cone-propeller hub-rear (bronze)	N-S
7	AN5007-20	Cone-propeller hub-front (steel)	N-S
8	AN5009-20	Ring-propeller hub-snap	N-S
16	41B-2328	Nut-propeller hub retaining	N-S
17	AN394-19	Clevis pin	F/N
	Attach hdw.	1 ea. AN960C-416, 1 ea. AN380-2-2	F/N

NOTE: Item 11 & Propeller assy. There are 4 different pitches on propellers
 98JA-56 for banner towing
 98JA-58 general purpose
 98JA-60 cross country
 98JA-62 R-755-9 Jacobs engine